

## NOTE:

This plan has been compiled from deeds, plans of record, assessors maps, and inspection of the property, for mortgage purposes only, and should not be construed as an accurate boundary survey, nor be recorded in the Registry of Deeds.

TITLE: Mortgage Inspection Plan

SCALE: 1" = 20

OWNER: Trumbull Realty LLC

LOCATION:

STREET: 6-8 Trumbull Rd. TOWN: Northampton COUNTY: Hampshire STATE: MA

DEED BOOK: 9451

PAGE: 159

PLAN BOOK:

4

PAGE: 62

REPORT TO: Monson Savings Bank & First American Title Insurance Company

I hereby report that this plan shows the results of a Mortgage Loan Inspection performed in accordance with the Technical Standards for Mortgage Loan Inspections adopted by the Massachusetts Association of Land Surveyors and Civil Engineers, Inc. Furthermore, I have inspected the premises shown hereon and appropriate deeds and plans of record. Accordingly, record easements and encroachments of buildings or improvements across boundary lines, if any, are indicated on the plan, and the buildings are not located within a Flood Hazard Area as defined on Federal Insurance Administration Maps.

7787tr01

INSPECTION AND PLAN DATE:

August 24, 2018

BY:

BRUCE BRUCE COOMBS No. 27814

HERITAGE SURVEYS, INC. COLLEGE HIGHWAY SOUTHAMPTON, MASSACHUSETTS